

From: [Moore, Gary](#)
To: leroy.cassidey@cbifederaleservices.com
Cc: ["gary.jones@swsenvironmental.com"](mailto:gary.jones@swsenvironmental.com)
Subject: CES: Work Activities for Week of March 16
Date: Sunday, March 15, 2015 9:03:00 AM

These are things I want done on Monday:

Monday, March 16:

Group 23 (Combustible Solids): 211 gal 3 containers – Vac Box

Group 24 (Flammable Liquids): 63 gal 2 containers – Vac Box

Group 25 (Flammable Solids): 42 gal 1 container – Vac Box ?

FT1004: Remove sludge/clean out and place in VB's used for Rejected Lonestar Load

FT215012/FT33527 (Sludge Removal/clean out)

Tuesday, March 17: Things I propose to have done on Tuesday – Additional items should be added

ST1 (Acid): Acid Removal into Totes

Group 7 (Acid): Acid Removal into Totes

You will need to complete the remainder of the week expectations and the order you want things done for me to review. I expect this to be a very complete week of activities with exceptionally high expectations.

Thanks

Gary Moore

Federal On-Scene Coordinator

U.S. EPA Region 6

214-789-1627 cell

214-665-6609 office

moore.gary@epa.gov